


HP ML350 G9 (350 EUR)



Locatie **Zuid-Holland, Zwijndrecht**
<https://www.advertentiax.nl/x-1903068-z>











Hierbij biedt ik mijn server aan.
 Het betreft een HP ML350 G9 en verkeerd in goede werkende staat.

Ik heb er altijd Proxmox (8.2.2) op gedraaid en dit staat er nu nog steeds op.

Specificaties:

Intel Xeon E5-2620 v4 @2,10 GHz 8 core 16 threads
 96 GB DDR4 RDIMM 2400 MHz (6x 16GB)
 HP Smart Array P420ar 2GB SAS Controller
 4x HP 300GB 10K SAS HDD
 4x 1GB Ethernet
 2x 500 Watt voeding
 ILO Advanced

ILO Health is gedegradeerd. Deze server heeft last van het de Embedded flash corruption bug.
 Dit betekend vooral dat je niet in de interactieve environment kan booten om je raid array te configureren,
 maar dat je dat via de CLI moet doen, of via de basic bios utility.
 Ook kan je geen virtuele media mounten om via ILO je OS te installeren. Mijn OS draaide op een losse

 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>	 <p>https://www.advertentiax.nl/x-1903068-z</p> <p>HP ML350 G9</p>
--	---	---	---	--	---	---	---	---	---